## Pattern Detail and Specifications

FLAMMABILITY:CALIFORNIA TECH TB117-2013 : UFAC:PASS CLASS 1DERFORMANCE:CLASS 1PERFORMANCE:Abrasion: Light Fastness:Average Min. 15000 Cycles Min. 40 Hours - Min. Class 3Color Fastness to CrockingWet: Image:	BESPOKE FBT		Color: Fiber Content: Fabric Repeat: Fabric Width: Fabric Backing: Fabric Grade: Fabric Direction: Country of Origin:	Willow 97% Polyester 3% Nylon N/A 54" Backed A RR China	
TB117-2013 : TB117-2013 :   UFAC: CLASS 1   PERFORMANCE:    Abrasion: Average Min. 15000 Cycles   Light Fastness: Min. 40 Hours - Min. Class 3   Color Fastness to Crocking Wet:   Wet: Min Class 4.0	FLAMMABILITY:				
Abrasion:Average Min. 15000 CyclesLight Fastness:Min. 40 Hours - Min. Class 3Color Fastness to CrockingWet:Wet:Min Class 4.0	<b>TB117-2013</b> :	r Abb			
Light Fastness: Min. 40 Hours - Min. Class 3 Color Fastness to Crocking Wet: Min Class 4.0	PERFORMAN	PERFORMANCE:			
	Abrasion: Light Fastnes	Light Fastness: Min. 40 Hours - Min. Class 3			
		Wet:			
		-			
CARE & CLEANING Cleaning Code: W			W		

"Spot clean only with water based shampoo or foam upholstery cleaner. Pretest a small, inconspicuous area before proceeding. Do not overwet. Do not use solvents to spot clean. Pile fabrics may require brushing with a non-metallic, stiff bristle brush to restore appearance. Hot water extraction or steam cleaning is not a recommended cleaning method. Cushion covers should not be removed and laundered. To prevent overall soiling, frequent vacuuming or light brushing with a non metallic, stiff bristle brush to remove dust and grime is recommended. When cleaning a spill, blot immediately to remove spilled material. Clean spots or stains from the outside to the middle of the affected area to prevent circling. Use a professional furniture cleaning service when an overall soiled condition has been reached."



1823 Eastchester Drive. High Point, NC 27265. USA www.Culp.com