## Pattern Detail and Specifications

| EAST LAKE |  |  | Color:<br>Fiber Content:<br>Fabric Repeat:<br>Fabric Width:<br>Fabric Backing:<br>Fabric Grade:<br>Fabric Direction:<br>Country of Origin: | Cream<br>98% Polyester<br>2% Nylon<br>n/a<br>54"<br>100% Polyester<br>A<br>Up the roll<br>China |
|-----------|--|--|--|---|
|           | FLAMMABILITY:                            |  |  |   |
|           | CALIFORNIA TECH<br>TB117-2013 :<br>UFAC: | PASS<br>CLASS 1                                  |  |   |
|           | PERFORMANCE:                             |  |  |   |
|           | Abrasion:<br>Light Fastness:             | Heavy Duty – 15,000 Cycles<br>40 Hours – Class 4 |  |   |
|           | Color Fastness to Crocking               |  |  |   |
|           |  | Wet:<br>Dry:                                     | Class 4.5<br>Class 4.5   |   |
|           | CARE & CLEANING                          |  |  |   |
|           | Cleaning Code:                           |  | W  |   |

"Spot clean only with water based shampoo or foam upholstery cleaner. Pretest a small, inconspicuous area before proceeding. Do not overwet. Do not use solvents to spot clean. Pile fabrics may require brushing with a non-metallic, stiff bristle brush to restore appearance. Hot water extraction or steam cleaning is not a recommended cleaning method. Cushion covers should not be removed and laundered. To prevent overall soiling, frequent vacuuming or light brushing with a non metallic, stiff bristle brush to remove dust and grime is recommended. When cleaning a spill, blot immediately to remove spilled material. Clean spots or stains from the outside to the middle of the affected area to prevent circling. Use a professional furniture cleaning service when an overall soiled condition has been reached."



1823 Eastchester Drive. High Point, NC 27265. USA www.Culp.com